


CORNER RECORD

Document Number CR 5398
 County of ALAMEDA, California

City of CASTRO VALLEY
 Brief Legal Description MONUMENT PRESERVATION SURVEY



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☐
 Date of Survey FEB 25-27, 2013

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PLAT
IN COMPLIANCE WITH SECTION 8771 OF THE PROFESSIONAL LAND
SURVEYORS ACT, THIS CORNER RECORD IS BEING FILED TO
ESTABLISH THE POSITION OF AN EXISTING MONUMENT PRIOR
TO STREET OR HIGHWAY CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset:


SEE PLAT.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MARCH 7, 2013

Signed [Signature] P.L.S or R.C.E. No. L6925



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3-11-2013

and examined and filed 6-10-2013

Signed [Signature] P.L.S or R.C.E. No. 5726

Title COUNTY SURVEYOR

County Surveyor's Comment _____



KUH11

